

Docket No.: 074077-0023

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of

Customer Number: 31824

David A. Rowe, et al.

Confirmation Number: 1174

Application No.: 10/806,682

Group Art Unit: 2618

Filed: March 22, 2004

Examiner: Pablo N. Tran

Patent No.: 7,155,193

Issued: December 26, 2006

For:

MULTI-CHANNEL FILTERING

SYSTEM FOR TRANSCEIVER

ARCHITECTURES

Certificate of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.323

Commissioner for Patents Office of Patent Publication ATTN: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

In reviewing the above-identified patent, printing errors were discovered therein requiring correction in order to conform the Official Record in the application. Some of the errors were made in the printing of the patent, and some of the errors were made by the Applicants in good faith and were of a clerical or typographical nature or of minor character.

The errors noted are set forth on the copy of form PTO/SB/44 (Rev. 09-07) in the manner required by the Commissioner's Notice.

02/13/2008 JADDU1

00000028 502203

7155193

61 FC:1811

160.00 DA

RECEIVED-USPTO Patent Publication

FEB 1 4 2008

U.S. Patent No. 7,155,193

Specifically, please note the following changes:

On the cover page, in (75) Inventors: Replace "Matthew D Pope" with -- Matthew D. Pope --.

In column 3, line 26, replace "coupled" with -- couple --.

In column 6, line 32, replace "(PHEMT)" with -- (pHEMT) --.

In the claims, claim 13, column 8, line 52, replace "The transceiver of claim 10," with -- The transceiver of claim 11, --.

Please charge the \$100.00 filing fee to our Deposit Account 502203. Please charge any shortage in fees due in connection with the filing of this paper to Deposit Account 502203 and please credit any excess fees to such deposit account.

Respectfully submitted,

McDERMOTT WILL & EMERY LLP

Please recognize our Customer No. 31824

as our correspondence address.

Soyeon Karen) Laub Registration No. 39,266

18191 Von Karman Ave., Suite 500 Irvine, CA 92612-7108

Phone: 949.851.0633 SKL:MMH

Facsimile: 949.851.9348

Date: February 11, 2008

ORC 432926-1.074077.0023

RECEIVED-USPTO

FEB 1 4 2008

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

		Page <u>1</u> of <u>1</u>
PATENT NO. :	7,155,193	
APPLICATION NO.:	10/806,682	
ISSUE DATE :	December 26, 2006	
INVENTOR(S) :	Rowe, et al.	
	d that an error appears or errors appear in the above-identified patent and the das shown below:	nat said Letters Patent
On the cover pa	ge, in (75) Inventors: Replace "Matthew D Pope" with Matthew D. Pope	 .
In column 3, line	26, replace "coupled" with couple	
In column 6, line	e 32, replace "(PHEMT)" with (pHEMT)	
In the claims, claim 13, column 8, line 52, replace "The transceiver of claim 10," with The transceiver of claim 11,		

MAILING ADDRESS OF SENDER (Please do not use customer number below):

McDermott Will & Emery, LLP 18191 Von Karman Avenue, Suite 500 Irvine, California 92612-7108

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria; S.D. VA 22313-1450.